

Survey Narrative To Comply With Paragraph 209.250 Oregon Revised Statutes

SURVEY FOR:

Harold Compton Route 3 Box 202 Medford, Oregon.

LOCATION:

The surveyed road is situated in the Southeast One Quarter (1/4) of Section 33 and the Southwest One Quarter (1/4) of Section 34, Township 37 South, Range 1 West, Willamette Meridian,

Jackson County, Oregon.

PURPOSE:

To monument and describe an easement for road

purposes.

PROCEDURE:

The Southeast and Southwest Corner of Donation Land Claim No.57, above Township and Range were found as indicated on the attached map. The "P" Line control established by the Jackson County Road Department for the North Phoenix Road was found as shown, the center line of the existing roadway was traversed and monumented in the location as indicated. Basis of bearings was Recorded Survey No. 810.

January 28, 1966



J. A. Hoffbuhr Registered Land Surveyor

