

## OREGON REVISED STATUTES

Survey for:

John K. Shults

467 Scenic Drive, Ashland, Oregon

Survey by:

Charles H. Hurst, L.S.

765 Sunrise Avenue, Medford, Oregon

Bearing:

Solar observation in confirmation of road centerline

bearing of D.R. 584-225 and 523-272

Purpose:

To monument and plat that tract of land to be known as

Clayton Creek Mobile Home Estates Subdivision.

## Procedure:

The road shown connecting the north boundary of the subdivision to Oregon 66 was established by holding centerline control previously established by L. E. Ager as identified by existing monuments found on centerline. These monuments have since been destroyed during the course of road construction. Reference is made to the road plan and profile submitted to the County Engineer showing the relationship of these monuments to the right-of-way monumented as shown on the official plat.

The west boundary of the subdivision south of the most northerly angle point coincides with the monumented line shown as a portion of a line defined by Recorded Survey 2138. 3/4" pins were set replacing the 1/2" pin monuments found. The northwest corner of the subdivision was monumented by driving a 3/4" iron pin replacing a 1/2" iron pin found and identified as that monument bearing S 12°53' W 26.55 feet from the northeast corner of Recorded Survey 2138. A line was held from the above monument through a 1/2" pin found Southerly 525.82 feet to a point of intersection with the line identified by Survey 2138 as running from the apex of a 30 foot lane Southerly 1040.27 feet.

The east boundary of the subdivision South of the section corner shown coincides with that line identified as the section line on Recorded Survey 2138. A line found running Northerly from the section corner was held in place and a 3/4" pin was set replacing a 1½" chromed exhaust pipe monument found on the fence line and identified as the northeast corner of the subdivision.

A search for the east quarter corner and northeast corner of Section 24 was unproductive. Accordingly, it was not determined if this segment of line coincides with the true section line.

A 3/4" capped pipe was found at the location of the southwest corner of D.L.C. 60. A stump hole was found in the northwest quadrant coinciding with record bearing and distance and some slight indication of a stump hole at record bearing and distance in the southeast quadrant. This corner fits within reason the official record and has been accepted as the official corner per Recorded Survey 2138. This monument falls S 41 42 15" E 55.48 feet and N 48 17 45" E 7.24 feet from the northwest corner of Lot 18, Block 3.

Drainages shown are well defined natural water courses. It is intended to incorporate in the restrictions pertaining to this subdivision provisions prohibiting the obstruction of such drainages and the right of access thereto for maintenance by duly constituted authority.

The southeast corner of D.L.C. 56 was found to be a 1½" iron pipe per Recorded Survey 1236, the location of which was checked and found extremely compatible with existing evidence in the area.


Boundary line control is based on previously surveyed lines and coincides with contract descriptions of adjacent properties with the exception of a segment of the west boundary which excludes a very small wedge of the client's property. This wedge will be granted to the adjacent owner at such time the existing contract is conveyed by deed.

Clayton Creek Mobile Home Estates Subdivision Page 2

The west quarter corner of Section 30 was found to be a 1" black iron pipe and a mound of stone. This corner has been in existence prior to 1945 and has been accepted as the official corner for both recorded and unrecorded surveys. The location of said corner was found campatible with the official record, although no evidence of the original witness trees was found.

Date:

MAR 4 1966



REGISTERED
OREGON
LAND SURVEYOR

OCTOBER 30, 1959
CHARLES H. HURST

Charles H. Bhrsz