

Survey No.

Survey Narrative to comply with O.R.S. 209-250:

Survey for: Clarence Olson

Rt. 4, Box 413-A Medford, Oregon

Survey by: Edward A. McGinty, L.S.

June, 1966

BASIS OF BEARING: Survey No. 2764.

PRECEDENCE OF SURVEY:

Found monuments set on previous survey No. 2764.

Calculated tie to the W. 1/4 cor. of Sec. 12, from said survey.

The control for the County road was determined from County P.I. hub which agrees with R.P.'s and R/W mon.

(P. I. hub was replaced with 5/8 in. iron pin)

A portion of Ingles survey shows line terminated with 3/4 in. iron pipes, a line ran parallel to an 20 ft. northerly

Monuments set being 5/8 in. x 24 in. iron pins, set approx. flush.

65-18



