

Survey No. 3197

Survey Narrative to comply with O.R.S. 209-250:

Survey for: Rogue Ranchos, Inc.
1133 So. Riverside
Medford, Oregon

Survey by: Edward A. McGinty, L.S.
June, 1966

BASIS OF BEARING: Solar Observation.

PRECEDENCE OF SURVEY:

At the NE. cor. of Sec. 32, found a 1 in. square pin set approx. 40 years ago, according to local residence, also found a stump hole southeasterly and probable sprouts from BT. tree. to the southwest a B.O. now about 20 ins. in diam. blazed about 30 years ago.

At the SE. cor. of Sec. 32 found B C pipe set on a 1921 survey by the BLM (Gen. Land Office).

Set 5/8 in. iron pins at proportional distance along section line.

This survey was made to determine the approx. exterior boundaries of the S. 1/2 of the S. 1/2 of the SE. quarter of the NE. quarter corner.

The client is aware of said conditions.

Monuments set being 5/8 in. x 24 in. iron pins, set approx. flush with the surface.

