

N.W. COR. D.L.C. # 42.7 T.395., R.IE., W.M. + ON 5"+6" STONE.

5/8" + 30" /RON BAR S.W. COR. D.L.C. #41

N.E.COR. D.L.C. #40.

T. 395., R. I E., W.M.

SURVEY NARRATIVE TO COMPLY WITH PARAGRAPH 209.250 OREGON REVISED STATUTES

SURVEY FOR: Carl Vogel, Ashland, Oregon.

RECEIVED
JUL 1 3 1967
SURVEYOR

LOCATION: D.L.C. # 40 & SW% Section 4, T.39 S., R. 1 E., W.M.

PURPOSE: To establish the boundary corners of tract of land as described in Title Policy.

PROCEEDURE: At NW corner of D.L.C. 42, found stone with +.

At SW corner of D.L.C. 41, found 3/4" iron pipe badly bent and rusted, replaced this pipe with a 5/8" + 30" rebar. As the description of the tract was tied to the above corner and the line between Claims No. 40 & 41, I established this line for my survey control.

Bearing datum: Solar taken May 1, 1967 at 2:30 P.M. Pac. Standard time.

Apparent decl. Adjusted Vertical angle Latitude

15°05.1' 50°41' 42°12'

Computed bearing of sun = $S. 56^{\circ}26'46"$ W.

D.L.C. Corner references set this survey

NW corner D.L.C. # 42.

A nail in root of a 21" Maple (SE face) 1.9 feet up, bears N. 15 33' E. 103.63 feet.

An iron rod %" + 24" bears North 115.97 feet, approx. southerly line of Hersey Street.

A 5" + 5" + ? Stone with lead center bears S.1°59' W., 10.68 feet, found in place.

A ½" + 24" iron rod bears South 103.70 feet.

Railroad spike in root of 26" Maple (Easterly face) bears S. 4 04' E. 102.42 feet, spike 3" up.

SW corner D.L.C. # 41 (West of centerline of Oak St.)

Center top fire plug bears N.57°50' E. 79.61 feet, plug on Ely. line of Oak St.

An + on Sly. rim man hole bears N.35° E. 69.85 feet.

A ½" + 24" iron rod at intersection of Sly. line Hersey St. & Wly. line Oak St. bears N.2 34' E. 24.24 feet.

A 2" + 24" iron pipe bears N.89 $^{\circ}$ 50' W. 3.42 feet.

A 3/4" iron pipe at property corner on Ely. line of Oak St. bears S.15°52' E. 48.62 feet (at intersect. fence lines.

REGISTERED OREGON LAND SURVEYOR

> MARCH 10, 1944 L. E. AGER 21