

from which a 4" White Oak, which bears N67 1/20E 133.3 feet, is double blazed and scribed W 1/16 S.1 RS 787 in the upper blaze and BT in the lower blaze. Also a 3 1/2" White Oak which bears S40°E 27.8 feet is double blazed and scribed W 1/16 S 12 RS 787 in the upper blaze and BT in the lower blaze.

5. For the South 1/16 corner common to Section 1 and Section 2, set a pipe stamped as shown below 2 inches in the ground to Lava Rock and surrounded with a mound of stone 3' x 3' x 30" high,

S2 | S1 1968

from which a 6 1/2" Incense Cedar, which bears N35°W 23.75 feet, is double blazed and scribed S 1/16 S 2 RS 787 in the upper blaze and BT in the lower blaze. Also a 8" Incense Cedar which bears S44 1/2°E 71.9 feet is double blazed and scribed S 1/16 S 1 RS 787 in the upper blaze and BT in the lower blaze.

6. For the Southwest 1/16 corner of Section 1, set a pipe 24" in the ground and stamped as shown below,

SW 1/16 S1

1968

RS 787

from which a 6 1/2" White fir bears N770E 9.6 feet. Also a 16" Douglas fir bears S12°W 36.8 feet. Both trees are double blazed and scribed SW 1/16 S1 RS 787 in the upper blaze and BT in the lower blaze.

7. For the Northwest corner of the property described in Deed Records Vol. 598 Page 319 - 320 parcel 1, set a pipe 16 inches in the ground and stamped as shown below.

> RS 787 PROPERTY CORNER 1968

8. For the Southwest corner of the property described in Deed Records Vol. 598 Page 319 - 320 parcel 1, set a pipe stamped as shown below 14" in the ground to lava rock and surrounded by a mound of stone 2 1/2 x 21 x 1 1/2' high.

> RS 787 PROPERTY CORNER 1968

The distance to all new bearing trees was measured to the face of the blaze and the compass variation was set at 20° East. The field work was completed August 29, 1968, by B. L. Brandt, Max Stockford, James Popham, and REGISTERED

Earl VanHoy.

BRICE L BRANDI

OREGON

SURVEYOR

RECORDED

CORNERS SET: Set corner pipes as indicated on the Survey Map.

1. For the center of the Section set a pipe 36" in the ground stamped as shown below.

As there were no trees within 200 feet, no bearing trees were scribed.

2. For the Center West one-sixteenth corner, set a pipe 27 imhes in the ground and stamped as shown below,

from which a 6" White Oak bears S33 $1/2^{0}$ W 4.3 feet. Also a 7" White Oak bears N11 $1/2^{0}$ W 25.9 feet. Both trees are double blazed and scribed CW 1/16 S.1 RS 787 in the upper blaze and BT in the lower blaze.

3. For the Center South one-sixteenth corner. Set a pipe 0 inches in the ground on lava rock and surrounded by a mound of stone $3' \times 3' \times 2 \ 1/2'$ high and stamped as shown below,

from which a 5 1/2" White Oak bears N73 1/2° E 18.0 feet. Also a 7" White Oak bears N85° W 31.8 feet. Both trees are double blazed and scribed CS 1/16 S.1 RS 787 in the upper blaze and BT in the lower blaze.

4. For the West 1/16 corner common to Section 1 and Section 12 set a pipe 1" in the ground and surrounded by a mound of stone 3' x 3' x 30" high and stamped as shown below,

SURVEY NARRATIVE TO COMPLY WITH O.R.S. 209.250, REVISED BY CHAPTER 555, O. L. 1963

FOR: BOISE CASCADE CORPORATION P O. Box 100, Medford, Oregon

PURPOSE: To subdivide the southwest one-quarter of Section 1, Township 33 South, Range 2 East, Willamette Meridian and to determine the property lines of that property described in the Deed Records of Jackson County Volume 598 Page 319 - 320.

PROCEDURE: Ran a transit traverse along the one-quarter section lines and closed around the Southwest one-quarter of Section 1. Set the one-sixteenth corners to the Southwest one-quarter section and traversed the one-sixteenth lines setting the Southwest one-sixteenth corner at the intersection thereof. Set the Northwest property corner and the Southwest property corner as called for in the deed and traversed the line between them.

CORNERS FOUND:

1/4 Corner $\frac{36}{I}$ - Found the 1" galvanized iron pipe with 1 1/2" expander filled with pot metal and marked "T.32 & 33 S $\frac{36}{I}$ 1/4 cor. 1952 C.S."7 inches above the ground as called for in the 1952 County Surveyor Re-establishment.

1/4 Corner $\frac{1}{1/2}$ - Found the 1" galvanized iron pipe 1 inch above the ground as called for in the 1940 County Surveyor Re-establishment. Also found one original B.T. and the C.S. B.T. with scribe visible on both.

SECTION CORNER $\frac{2}{1/2}$ - Found the 2" iron pipe 3 inches below the ground as called for in the 1929 County Surveyor Re-establishment. Also found the 12" Black Oak bearing tree scribed in 1929 and the Douglas fir bearing tree and the Incense Cedar bearing tree as called for in the 1957 re-establishment by the County Surveyor.

1/4 Corner 2 1 - Found the original NW bearing tree now a 20" live, standing Ponderosa pine with scribing visible and the original NE bearing tree now a 24" Ponderosa pine stump with scribing visible. Also found a 1" galvanized iron pipe with 1 1/2" expander filled with pot metal and marked "T33S, R2E 2 1 1/4 cor." 10" above the ground 1.7 feet from its proper location. I moved the pipe to the proper location for the corner from which the original NW Ponderosa pine bearing tree bears N58°W 19.8 feet and the original NE Ponderosa pine stump bears N7 1/2°E 52.8 feet. To the pipe I added the marks "RS 787" and scribed an 18" Douglas fir which bears S84°E 32.2 feet from the corner.

1/4 Corner 1 6 - Found the 1" galvanized iron pipe flush with the surface of an existing road as called for in the re-establishment by the County Surveyor in 1953. As the top of the pipe has been bent over I used the center of the pipe below the bend as the point for the corner. Also found the two County Surveyor bearing trees scribed in 1953 with the faces closed.