

page 3 of 3

Original corner - October 1854 A charcoal post was set

1910 road survey by Brown, Bk. 3, page 45 found stone with a X in the center of road.

1945, county surveyor set a proportional 1/4 corner approx. 9 ft south of the center of the old existing road.

1969 - Jan. 21.

Found the stone, shown on the 1910 road survey, approx. 6 ins. deep,  $4" \times 6" \times 8"$  with X on the top in the approx. center of the existing road. Set reference points and removed stone, found several bits of charcoal and decayed wood.

From reference points, set a 5/8 in. iron pin, 24 ins. long, 8 ins. deep for the original 1/4 corner. Replaced a few bits of charcoal along the northside and a stone along the east side of an iron pin, from which

An east-west fence bears North 22 feet An east-west fence bears South 20 feet County survey proportional corner being a 1 in. iron pipe, 16 ins deep, bears S. 4 3/4° W., 9.17 ft.

Notified V. Thomas, local surveyor, as to the conflict which may arise on survey No. 3452.

The north-south center line of the Section was determined by the SW. 1/4 corner found in 1910 and recovered by this survey and previously mentioned as the 1/4 corner between Section 14/23.

The east-west center line of the Section was determined by the W. 1/4 corner and a line extended from a 5/8 in. iron pin, 4 ins. deep, set for the center of Section on Survey No. 3452.

## Monuments:

Monuments set on previous survey No. 1528 and an unrecorded survey by H. Ingle, being 1/2 in. rebar, set 2 ins. to 6 ins. above the ground.

WAR 6 1969

OF VEYOR

REGISTERED
OREGON
LAND SURVEYOR

EDWARD A. McGINTY 301

M. Tin

Page 2 of 3

The Section corner, 14, 15, 22 and 23.

Found a 2 in. iron pipe, 12 ins. deep.

The center line of Dodge Road was determined from county road data and monuments found being 5/8 in. iron pins at the 1/4 cor. between Sec. 15/22 and a spike approx. 12 ins. deep at the intersection of Antioch Road., from which (County road R.P. 's)

A 1/2 in. iron pipe, bears S.68° 07' E., 42.88 ft. A 1/2 in. iron pin, bears S.51° 25' W., 50.30 ft. A 3/8 in. x 1 3/4 in. iron bar, bears N.38° 12'W., 63.31 ft. A 3/4 in. iron pin, bears N.31° 21'E., 77.33 ft.

The center line of Antoch Road was determined from county road data and monuments found. The 1/4 cor. between Sec. 14/23 and Dodge Road intersection, previously previously described. At county station 212 + 34.50, found a 5/8 inch iron pin, 40.0 ft. westerly and 39.91 feet easterly. At county P.C., station 218 + 81.0, found a 5/8 in. iron pin, S.89° 40' 30" E., 40 ft. and a 5/8 in. iron pin, N.89° 40' 30" W., 40 ft. and on tangent 0.58 ft. southeast of county station 223 + 25.8. Found a 5/8 in. iron pin, N.72° 28' 20" East, 40 ft. and a 5/8 in. iron pin. S.72° 28' 20" West, 40 ft. At county station 257.+ 04.30 found a 1/2 in iron pin. 27 ins. deep station 257.+ 04.30 found a 1/2 in. iron pin, 27 ins. deep.

Survey No.'s 1514 and 2337 are in conflict with survey No. 1528, an unrecorded survey by H. Ingle, as to the location of the East-west denter line of Section 14, and this survey is in conflict with all above mentioned surveyes on this line.

Survey No. 1514, shows a sub-division of the East 1/2 of the SW. 1/4, the tracts holding the fence line along the west line. The descriptions were prepared from survey No. 1514 making a possible title encroachment on The property to the west, also the descriptions prepared, indicate Antioch Road being a 60 foot road (note, mape scale approx. 60 ft.)

A revised map (unrecorded) by the same surveyor, indicates Antioch road to be 80 feet and monuments found are approx. 40 ft. from center line.

In Section 14, the controlling boundaries are Dodge Road and Antioch roads, the east-west and north-south center line of Section 14 and the west line of the East half of the Southwest quarter.

PART 2

SECTION 23, T35S, R2W.

West 1/4 corner.

Found a l in. brass cap set by the county surveyor, apparently the distance as reported by the county surveyor is to be taken to the face of bearing tree's instead of enter of tree's.

The South 1/4 corner.

After a discussion with the county surveyor, I researched this corner and found.

(next page)

## SURVEY NARRATIVE TO COMPLY WITH O.R.S. 209-250

Survey for:

Cal-Ore Ranches 1054 South Riverside Medford, Oregon

Survey by:

Edward A.McGinty, R.S.

Medford, Oregon February, 1969

Basis of Bearing:

Antioch County Road

Precedence of Survey:

This survey is a partial retracement of Survey No. 1528 and an unrecorded survey by Hugh Ingle, located in the East half of the SW. 1/4 of Sec. 14 and the NW. 1/4 of Sec. 23.

## PART 1

SECTION 14, T35S, R2W:

At the 1/4 corner between Section 11/14, found a 1 in iron pipe, 12 ins. deep, from which I found

A 5/8 in. iron pin, bears southerly, 40.05 ft. A 5/8 in. iron **pin**, bears northerly, 39.95 ft.

At the 1/4 corner between Section 14/23, set tack from R.P.'s

Found 5/8 in. iron pin which bears N.89° 52' W., 40 ft. Found 5/8 in. iron pin which bears S.89° 52' E., 40 ft. Found a wh. oak, 14 ins. dia., bears S.39° 20' E., 106.8 ft.

At the 1/4 corner between Section 14/13.

Found a stone 3 x 3 ins. x?, 2 ins. above the ground, marked with an X, from which

A stump of a white oak, bears N.26° 02' W., 161.10 ft. The east fork of a white oak, 14 ins. dia., bears S.43° 07' W., 62.3 ft., with 2 blazes.

A 1/2 in. iron pin, bears N.89° 55' 20" W., 508.29 ft. dist. A white oak, 18 ins. dia., bears N.3° 25' W., 248.60 ft. with 2 blazes (not scribed)

At the 1/4 corner between Section 15/14.

Found a l in. iron pipe, 3 ins. above the ground, at the north side of the fence corner, from which (bearing tree's measured distance only)

A white oak, 10 ins. dia., bears southeasterly, 26.7 ft. A pine, 30 ins. diam., bears northeasterly, 104.0 ft.

At the 1/4 corner between Section 15/22

Found a 5/8 in. iron pin, approx. center of pavement.

8465-SHEET 2 OF 2 12 R=2894.79 L= 264.15 \$84 °38'40" W 433.60 Fd. C-L-DODGE RD. 1/4 Cor. N 0 0 0 2 25" W 333.26 Fd 10 9 S.15 | S.14 1323.90' N89°52'25"E 2647.80' 40' 40' 1/4 Cor. S.22 S.23 8.92\_ 590.86 692.65 N 89°58' 00"W 1283.31' 1282.04 S 89°57' 20"E 1281.17 N89° 58' 30"W 2655.42 1280.29' \$ 89°58'00"E S 0005'10"W 1279.42 N 89°57'40"W 3.38 1.83 1278.53 \$89°57'30"E 0.31 1277.66 N 89°57'50"W 291.20 2 1276.80 S 89° 5 7' 55' E 45.33 1=251.36 R\$1949.86 1/4 Cor. 1292.08,<sup>1</sup> /21.259.65 Wit. Cor. 1321.88 N89°55'30"W 2643.76' Fd. Co. PI. Boat Spike SURVEY IN NW. 1/4 Sec. 23,T355, R.2W., WM. FOR FAYDREX INC. 69 + 2 - 2 1/4 Cor. BY EDWARD A. MC GINTY SCALE I" = 200' o = Mon. Fd . See Nar. MEDFORD, OREGON FEBRUARY Fd 1910 Cor. ● = 5/8"1.Pin Set S RECORDED REGISTERED OREGON LAND SURVEYOR MAR 6 1969 \_3948 CRVEY EDWARD A. McGINTY