

Butte Falls, Oregon
September 22, 1969

County Surveyor
Jackson County Courthouse
Medford, Oregon

Dear Sir;

Record following in Public Land Surveys.

SUBJECT; Section 12, T.34S, R2E, W.M.

OBJECT; Remonument existing corners destroyed during logging.

For; Medford Corporation.


W 1/16 corner Sec. 1/12. Fnd. RS 461 pipe & cap, BTs.
SE BT down. Scribed RS 461 BT 10" Yew S9°W 33.6'

N 1/16 corner Sec. 11/12. Fnd. RS 461 pipe & cap, BTs.
SE BT down. Scribed RS 461 BT, 9" W.Fir S10°W 22.9'

C 1/4 corner Sec. 12. Fnd. RS 461 pipe & cap, BTs.
Scribed RS 461 BT, 5" Dogwood S12°WW 24.7'

C-S 1/16 corner Sec. 12. Fnd. RS 461 pipe & cap, BTs.
Scribed RS 461 BT, 10" W.Fir S81°E 24.8'

E 1/4 corner Sec. 12. Fnd. RS 461 BTs, pipe & cap.
Scribed RS 461 BT, 14" Chinguapin
Due North 35.0'



Duane A. Smeltzer

