

4476

# PLAT

Scale: 1" = 400'

Showing a survey of the West 1/2, East 1/2, S.E. 1/4, S.W. 1/4, of Sec. 9, T. 35 S., R. 4 W., W.M. Jackson County, Oregon

NORTH

Set 1/4<sup>th</sup> Cor. from which an 18" laurel bears S. 35° W. 47.0', scribed 1/4<sup>th</sup> B.T.

Fd. 1/4" I. Pipe + B.T.'s as per Co. Survey Rec. # 121 for 1/4<sup>th</sup> Cor.



Fd. 1/4" I. Pipe + B.T.'s for 1/4<sup>th</sup> Cor. as per County Survey Rec. # 121. Said pipe 16" below surface. Set 1/2" x 24" Iron Pin in center of said pipe 4" below surface.

Surveyed March 8, 1966

For  
 Gordon Harrison  
 RT. 1 Box 234<sup>x</sup>  
 Rogue River, Ore.

by  
 S. S. Smythe  
 1210 S. E. Rogue Dr.  
 Grants Pass, Ore.

T 35 S

N. 00° 22' E (Rec. B.T.)

S. 00° 22' W (Rec. B.T.)

Indicates Lines run

● Indicates 1/2" x 24" Iron Pins set in This survey

Fd. Sec. Cor. Car Axle + B.T.'s as per 20-section Co. Surveyor



Set 1/4<sup>th</sup> Cor. from which a 24" Y. Pine bears S. 27° E. 23.5', scribed 1/4<sup>th</sup> B.T.

Set 1/4<sup>th</sup> Cor.

Fd. 1" Iron Pipe as per Co. Survey Rec. Re-est. # 121

JACKSON COUNTY  
 RECORDED  
 FEB 23 1971

REGISTERED  
 OREGON  
 LAND SURVEYOR

S. Sidney Smythe

NOVEMBER 11, 1960  
 S. SIDNEY SMYTHE  
 525

I do here by certify and attest that this is an exact copy of the original survey as executed above and a plat of.  
 R. 4 W.  
 S. Sidney Smythe