

SURVEY NARRATIVE TO COMPLY WITH O.R.S. 209-250

Survey for:

71-27

Faydrex, Inc. 1054 So. Riverside Ave.

Medford, Oregon

Survey by:

Edward A. McGinty, R.S.

Medford, Oregon August 1971

Basis of Bearing:

Solar Observation

Location:

NE. 1/4 of SW 1/4 of Sec. 30, T36S, RAW.

Precedence of Survey:

A. Found 1 1/4 in. iron pipe approx. 14 ins. deep (note, $1\frac{1}{2}$ "OD) being the same as shown on survey No.s 3850 and 3430 as the 1/4 cor. betw. Sec.s 19 and 30. This corner re-est. by the county surveyor in 1937 calls for 2" pipe.

The south line of the tract surveyed is dependant on old hubs found being identified as original lot corners of the Savage Lake Tracts by local resident of about 20 yrs. which were identified to him by previous owners. Found a shortage existing along this fine. Witness corners were set at a prorationed distance between corner hubs found and mean average of the northerly 3 corner stake.

Adjacent owners, according to improvements such as old fence line, etc., have accepted hubs as lot corners for approx. 30 years.

Monuments set near the north side of lots were dependant on old fence lines, as best available evidence of lot line. Note, this area has been flooded several times and the highway changed since original tracts were surveyed. Procedure of this survey method in determining lines surveyed was explained to client.



REGISTERED OREGON LAND SURVEYOR

Twent a. M. Tinty EDWARD A. MCGINTY 301