



PROPERTY SURVEY
 SITUATE IN
 SW 1/4 SEC 4 & SE 1/4 SEC 5 T 35S R 4W WM
 JACKSON COUNTY OREGON
 G W PLUMB LAND SURVEYOR MEDFORD OREGON
 SCALE 1" = 200' 25 JULY 1972

Survey for H. A. Flook
9386 West Evans Creek Road
Rogue River Oregon 97537

P. J. Schuster
9458 West Evans Creek Road
Rogue River Oregon 97537

Survey by G. W. Plumb Land Surveyor
P. O. Box 904
Medford, Oregon 97501

Location Southwest Quarter of Section 4, Township 35 South, Range 4 West
Southeast Quarter of Section 5, Township 35 South, Range 4 West
of the Willamette Meridian, in Jackson County, Oregon.

Found 3/4" pipe, with bearing trees, at 1/4 corner of Sections 4 and 5, T. 35 S., R. 4 W., W. M., and 3/4" pipe with bearing trees, set per Record Survey No. 3766 for the S. 1/16 corner of sections 4 and 5. Found 5/8" iron rods set per Record Survey No. 4775, as shown on the accompanying map. Set additional 5/8" iron rods as shown on said map, as requested by the owners of the respective properties. The south line of the property in Section 5 falls in a ditch; the rods for this line were set as witness corners, as shown on the map, 15.00 feet from the true corner positions.

