

5098-A

5098-

OLD STAGE ROAD

FND 5/8" IRON ROD  
 196.06'  
 NW COR DLC 44  
 FND 1/2" PIPE  
 S 89° 11' 20" E  
 REC EAST  
 N 89° 58' E 353.00'  
 S 89° 11' 20" E 353.04'  
 SW COR DLC 54  
 FND BRASS DISC  
 IN MON CASE

REC NORTH  
 N 0° 39' 10" W 212.42'  
 196.92'  
 REC WEST  
 S 89° 58' W 353.00'  
 REC SOUTH  
 S 0° 39' 10" W 212.42'  
 191.72'

JACKSON COUNTY  
 RECEIVED  
 FEB 15 1973  
 SURVEYOR

REGISTERED  
 PROFESSIONAL  
 LAND SURVEYOR  
 GREGON  
 JULY 12, 1968  
 G. W. PLUMB  
 862

0 SET 5/8" X 24" IRON ROD  
 BEARINGS FROM R S 3863  
 SCALE 1" = 100'

PROPERTY SURVEY  
 SITUATE IN  
 DLC 44  
 SW 1/4 SEC 9 T 37 S R 2 W WM  
 JACKSON COUNTY OREGON  
 G W PLUMB LAND SURVEYOR  
 MEDFORD OREGON 14 FEB 1973

5098-

Survey for: Gary Merrill  
3055 Beall Lane  
Central Point, Oregon 97501

Survey by: G. W. Plumb, Land Surveyor  
P. O. Box 904  
Medford, Oregon 97501

Location: SW  $\frac{1}{4}$  Section 9; D. L. C. 44; Township 37 South, Range  
2 West of the Willamette Meridian, Jackson County,  
Oregon.

Found 1 $\frac{1}{2}$ " iron pipe for NW. corner of D. L. C. 44; brass disc in iron  
monument case for SW. corner of D. L. C. 54; 3/4" pipe on the West line  
of Sunnydale Drive; 5/8" iron rod at centerline intersection of Beall  
Lane and Old Stage Road. Set 5/8" x 24" iron rods for corners of Jackson  
County Record No. 72-05146, using the line southerly from the NW corner  
of D. L. C. 44 per Record Survey No. 2782 for control.

