

BY EDWARD MC GINTY
 MEDFORD, OREGON
 JUNE 1972

SURVEY IN NW. 1/4 SEC. 32, T. 37S. R. 2W. WM
 IN CITY OF JACKSONVILLE
 FOR
 DON WENDT
 72-14

SCALE 1" = 50'
 Mon. Set 5/8" I. Pin
 Mon. Pd. See Nor.

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR
 OREGON
 JULY 10, 1953
 EDWARD A. MCGINTY
 901

JACKSON COUNTY
 RECEIVED
 MAR 20 1973
 SURVEYOR

SURVEY NO. 5131

SURVEY NARRATIVE TO COMPLY WITH O.R.S. 209-250

Survey for: Mr. Donald Wendt 72-14
Jacksonville,
Oregon

Survey by: Edward A. McGinty, R.S.
Medford, Oregon
June 1972

Location: NW. 1/4 of Sec. 32, T37S, R2W
City of Jacksonville

Precedence of Survey:



Monuments:

- A. Found rail spike
- B. Found 5/8 in. iron pin, approx. 1 ft. deep
- C. Found Spike
- D. Found 3/4 in. iron pin
- E. Found 3/4 iron pin.

Monuments set being 5/8 in. x 24 in. iron pins, set approx. flush with the surface.

The monuments set near the northerly line, being witness corners.

Monuments along the westerly side, being on the line surveyed, as shown, for a proposed line agreement.



Edward A. McGinty
OREGON
JULY 10, 1973
EDWARD A. MCGINTY
301