



BEARINGS FROM R S NO 1220
 ● FND 5/8" IRON ROD
 ○ SET 5/8" X 24" IRON ROD

JACKSON COUNTY
 RECEIVED
 APR 26 1973
 SURVEYOR

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

G. W. Plumb

OREGON
 JULY 12, 1968
 G. W. PLUMB
 862

PROPERTY SURVEY

SITUATE IN

DLC 73

E 1/2 SEC 23 T 37 S R 2 W WM

JACKSON COUNTY OREGON

G W PLUMB LAND SURVEYOR

MEDFORD OREGON

SCALE 1" = 200'

22 APRIL 1973

Survey for: Joe E. Brooks
270 $\frac{1}{4}$ Stearns Way
Medford, Oregon 97501

Survey by: G. W. Plumb, Land Surveyor
P. O. Box 90 $\frac{1}{4}$
Medford, Oregon 97501

Location: E. $\frac{1}{2}$ Section 23, in D. L. C. No. 73, in T. 37 S., R. 2 W., W.M.

Found 5/8" iron rods at the N.W. and S.W. corners, and at the west end of Stearns Way, in Weldon Subdivision, and at the N.W. and S.W. corners of Registered Survey No. 1220.

Set 5/8" X 2 $\frac{1}{4}$ " iron rods as shown on the accompanying map, as requested by the owner.

22 April 1973

