


Reference Points Found
P.K. Nails on ϕ
(Mon. Case Fd. with Hub & tack)



Survey For
John Hamlin
Block 18, Original Town of Medford
S.E. 1/4 Section 30, T.37S, R.1W, WM.
By Edward McGinty
Medford, Oregon
March, 1973

Scale: 1"=50'
● Monuments Set as shown
○ Monuments Found as shown

REGISTERED
PROFESSIONAL
LAND SURVEYOR
Edward A. McGinty
OREGON
JULY 10, 1953
EDWARD A. MCGINTY
301

JACKSON COUNTY
RECEIVED
MAY 10 1973
SURVEYOR

Survey No. 5223

SURVEY NARRATIVE TO COMPLY WITH O.R.S. 209-250

Survey for: John Hamlin 73-5
Hamlin Motor Co.
E. 9th & S. Central
Medford, Oregon 97501

Survey by: Edward A. McGinty, R.S.
Medford, Oregon
March, 1973

Location: Blk. 18, Original Town of Medford
S.E. 1/4 of Sec. 30, T37S, R1W

Precedence of Survey:

Surveyed boundary line as shown from monuments found at 10th and Front Street intersection, determined city reference which is in monument case. (Found nail straddles)

9th and Front Street- found 1 inch iron pin in monument case.

9th and Central Street- found monument case and concrete monument.

10th and Central Street- found monument case and concrete monument.

