



BEARINGS FROM SUN ALTITUDE
 O SET 5/8" X 24" IRON ROD

REGISTERED
PROFESSIONAL
 LAND SURVEYOR
G. W. Plumb
 OREGON
 JULY 12, 1968
 G. W. PLUMB
 862

PROPERTY SURVEY
 SITUATE IN

SE 1/4 SEC 2 T 37S R 4 W WM
 JACKSON COUNTY OREGON

G W PLUMB LAND SURVEYOR MEDFORD OREGON
 SCALE 1" = 100' 26 JUNE 1973

JACKSON COUNTY
 RECEIVED
 JUL 3 1973
 SURVEYOR

Survey for: Glenn V. DeJanvier
2141 Foots Creek Road
Gold Hill, Oregon 97525

Survey By: G. W. Plumb, Land Surveyor
P. O. Box 904
Medford, Oregon 97501

Location: SE $\frac{1}{4}$ Section 2, T. 37 S., R. 4 W., W.M.

Found 2" iron pipe for corner of Secs. 1, 2, 11 and 12. Found $\frac{1}{2}$ " iron pipes on southwesterly right of way of the road, per R. S. 1839. Found 5/8" iron rod on easterly right of way line, and iron axle with gear, on North line of property, per R. S. 3533. Found iron bolt on East line of R. S. 2870, and 5/8" iron rod at NE corner of property, instead of 3/4" iron rod as shown on R. S. 2870. The bolt was found to be 0.94 feet east of the line from the section corner to the NE. corner. Set 5/8" x 2 1/4" iron rods as shown on the attached map to divide the property as requested by the owner.

