


PROPERTY SURVEY
 SITUATE IN
 NE 1/4 SEC 1 T 36 S R 2 W WM
 JACKSON COUNTY OREGON
 G W PLUMB LAND SURVEYOR
 MEDFORD OREGON 3 DEC 1973



- BEARINGS FROM RS 1900
- FND 5/8" IRON ROD
- SET 5/8" X 24" IRON ROD
- SCALE 1" = 200'

REGISTERED
PROFESSIONAL
 LAND SURVEYOR
G. W. Plumb
 OREGON
 JULY 12, 1968
 G. W. PLUMB
 862

5482

Survey for Ralph B. Leiby
10610 Antioch Road
Central Point, Oregon 97501

Survey by G. W. Plumb, Land Surveyor
P. O. Box 904
Medford, Oregon 97501

Location NE $\frac{1}{4}$ Section 1, T. 36 S., R. 2 W., W.M., Jackson County,
Oregon


Found $\frac{5}{8}$ inch iron rods marking the center north sixteenth, and the center quarter corners of Section 1. Found $\frac{5}{8}$ inch iron rods at the three other corners of the south parcel, per Jackson County Registered Survey Number 1900. Cheked the lines of the survey and set additional corners as requested by the client, as shown on the accompanying map. North-South distances checked closely with Survey Number 2248; East-West distances were closer to Survey Number 1900.

3 December 1973

REGISTERED
PROFESSIONAL
LAND SURVEYOR

G. W. Plumb

OREGON
JULY 12, 1968
G. W. PLUMB
862



S. 1 T. 36 2 W