

Survey No. 5598

Jackson County Surveyor
Edward A. McGinty
Medford, Oregon

Subject: Re-establishment of 1/4 corner common to sections $\frac{4}{9}$ T40S,
R04E, W.M.

Set a 5/8" x 30" Iron Rod from the B.T.s as described by the County
Surveyor on 26 Nov., 1929.

A Yellow Pine 24" in diameter, bears S46°30'W, 36.0 Lks. (B.T. is
now 24" in diameter)

A Red Fir 14" in diameter, bears N54°30'E, 62.1 Lks. (B.T. is now
24" in diameter)

A SurvKAP was set atop the 5/8" x 30" I.R. and was stamped,

WEYERHAEUSER

1/4 $\frac{S4}{S9}$

1970
ORLS 686

and from which bears:

A 'W' nail set in the base of a Douglas Fir 10" in diameter,
that lies S07°W, 57.4 Lks. distance.

A 'W' nail set in the base of a Douglas Fir 9" in diameter,
that lies N35°W, 21.3 Lks. distance.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Everett J. Scott

OREGON
JULY 10, 1964
EVERETT J. SCOTT
661

