

6271

MAP OF SURVEY
LOCATED IN
SW 1/4 OF SEC. 11, TWP. 39S, R. 1E, W. M.
JACKSON COUNTY OREGON
FOR

MRS. ANITA PARENT



EVERETT L. SWAIN, R.L.S. ASHLAND, OREGON

SCALE 1" = 100'


BASIS OF BEARING:

NOVEMBER 25, 1974
REVISED FEBRUARY 3, 1976
N. O. A. A. TRUE BEARING N-S & SEC. 11

- FOUND MONUMENTS AS SHOWN
- SET 5/8 x 30 INCH IRON PIN WITH ALUM. CAP



SECTION CORNER
LOCATION DETERMINED
FROM PREVIOUS TIE TO
THE ASHLAND CONTROL NET



RELOCATED GREEN SPRINGS HIGHWAY (HIGHWAY No. 66) 1327.64'
S 89°54'06" E
S 89°52'50" E

RECORDED SURVEY
No. 4941

RECORDED SURVEY
No. 4665

HERTHA C. WEISETH
LAKEWOOD PARK, SP. B1
EUGENE, OREGON 97402

HERBERT D. WYCKOFF
CONTRACT OF SALE
IRENE MEGGERS
ROYAL OAKS
HOME, SA 58 MOBILE
4089 S. PACIFIC HWY
MEDFORD, OREGON
97501

L. L. & LOYS LOUISE TAYLOR
380 CLAY STREET
ASHLAND, OREGON 97520

RICHARD J. & BARBARA J.
MEISTER DR
1777 CRESTVIEW DR
ASHLAND, OREGON 97520

FD. 5/8" I. PIN
W/TAG R.L.S. 759
Re: R.S. No. 5613

BOUNDARY
LINE AGREEMENT
INSTRUMENT NO. 75-15343
O.R. J.C.O.

FD. 3/4" PIPE
W/PINCHED TOP

N. 89°17'32" E. 211.93'

100.00'

469.47'

300.00'

N. 00°13'00" E.

69.47'

FD. 5/8" I. PIN
W/ALUM. CAP
BRS. N. 89°52'50" W.
0.53'

N. 89°52'50" W.
10.67'

FD. 5/8" I. PIN
W/ALUM. CAP
OSHD.


FD. 5/8" I. PIN
W/ALUM. CAP
OSHD.

OREGON STATE
HIGHWAY COMMISSION

FD. 5/8" I. PIN
W/ALUM. CAP
OSHD.

1/4 SEC. COR.
LOCATION DETERMINED
FROM PREVIOUS TIE
TO THE ASHLAND
CONTROL NET

FD. PK NAIL
PER STATE HIGHWAY



6271

SURVEY NO. 6271

SURVEY NARRATIVE TO COMPLY WITH PARAGRAPH 209.250
OREGON REVISED STATUTES

SURVEY FOR: Anita Parent
2205 Highway 66
Ashland, Oregon 97520


LOCATION: Situated in the Southwest quarter of Section 11, Township 39 South,
Range 1 East of the Willamette Base and Meridian, Jackson County,
Oregon.

PURPOSE: To survey and monument the boundaries of the parcel as shown on the
accompanying map.

PROCEDURE: With the legal subdivision of Section 11 needed in order to establish
the true boundaries of the clients parcel of land, it was recommended
that various found monuments and existing improvements be utilized
for the securing of boundary lines by agreement. The boundary lines
were recently agreed upon and the document filed of record.
Monumented the parcel as shown on the accompanying map.

February 3, 1976

Everett L. Swain
Professional Land Surveyor
Ashland, Oregon



S11 T39 R1E