



PROPERTY SURVEY
 SITUATE IN
 SW 1/4 SEC 27 T 37S R 1W WM
 JACKSON COUNTY OREGON
 G W PLUMB LAND SURVEYOR
 MEDFORD OREGON 15 AUG. 1976

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

G. W. Plumb
 OREGON
 JULY 12, 1968
 G. W. PLUMB
 862

JACKSON COUNTY
 RECEIVED
 SEP 13 1976
 SURVEYOR

SCALE 1" = 100'
 * FOUND MON AS SHOWN
 ○ SET 5/8" X 24" IRON ROD
 ● SET 5/8" X 30" IRON ROD
 BEARINGS FROM RS 1227

Survey for Walter J. Young
Medford Stationery Store
525 South Central
Medford, Oregon 97501

Survey by G. W. Plumb, Land Surveyor
P. O. Box 904
Medford, Oregon 97501

Found 2" iron pipe at the NW. cor. of Fair Oaks Orchards Tracts in the SW. quarter of Section 27, T. 37 S., R. 1 W., W.M. Found 5/8" iron rod at the SW. cor. of Lot 2 of said Tracts, and 1/2" iron pipe at the NW. cor of Lot 20. Found 5/8" iron rod on N. line of 40 foot road, per R. S. 1227. Using these monuments for control, set 5/8" iron rods as shown on the accompanying plat to segregate a five acre tract.

15 August 1976

