

© S.W. Cor. D.L.C. No. 59 T37SR2W

S 89° 54' 45" E 1834.14
(Survey no. 1143 Record)



SCALE 1"=50'

Basis of Bearings R.S.No. 1143


LEGEND

- = Set 1" x 30" Galv. Iron Pipe
- = Found monument as noted

REGISTERED
PROFESSIONAL
LAND SURVEYOR

George Burrell

OREGON
JULY 10, 1964
GEORGE R. BURRELL
638



MAP OF SURVEY

Located in N.W. 1/4 Sec. 13, T37S, R2W
For: BYRON LAMBERT
By: George Burrell, Surveyor, 2/18/77

0096
SURVEY NO. _____

SURVEY NARRATIVE TO COMPLY WITH O.R.S. 209.250

FOR: Byron Lambert
 2576 Merriman Road
 Medford, Oregon

PURPOSE: To monument and describe that portion of the clients
 ownership as shown on the accompanying map.

PROCEEDURE: The monuments found or set by recorded survey no. 1143
 were recovered and held as control in establishing the
 Northerly, Easterly and Westerly boundaries.
 The Southerly boundary established by my survey was
 located according to the clients instructions.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

George R. Burrell

OREGON
JULY 10, 1964
GEORGE R. BURRELL
638

