

## SURVEY NARRATIVE TO COMPLY WITH O.RS. 209-250

Survey for:

Orin Frederick

and John Clever

75-33

981 7th Ave. Gold Hill, Or.

675 9th St.

Gold Hill, Or. 97525

Survey by:

Edward A. McGinty, R.S.

Medford, Oregon= December, 1977

Basis of Bearing:

S.P.R.R. center line N.77°18'W.

Location:

Basically in the SE. of the SE. quarter of Sec. 16,

T36S, R3W., WM. City of Gold Hill

Dependent Survey:

This survey was made with FDM equipment and chain with open ended traverse to the section corner.

At the Northeast corner of Sec. 16 found a 1 in. pipe and B C; thence traversed southerly to a point of a proportional distance in an area of semiopen, apparently several fires have occured since the original survey. I made a thorough search and found no evidence of the original B T, although similar species of sprouts and younger trees were in the general area, it would be more imaginary to assume any direct relation to the original corner location - Set a 5/8 in. x 24 in. iron pin at a porportional distance for the 1/4 corner betw. Sec's 15 and 16, from which

A white oak 8 ins. diam., bears S.9°19'W, a dist. of 19.1 ft. (2 blazes only)

A white oak, 14 ins. diam., bears S.89°29'W., " 65.3 £t. (2 blazes only)

Commencing at the SW cor. of Sec. 16 traversed to the NF cor. of said Section and made a search for evidence of the orig. BY, this falls in a semi open area where previous wood cutting and clearing has taken place, finding no evidence set a 5/8 in. x 24 in. iron pin at a proportional distance from which

A white oak, 14 ins. dia. bears S.53°35°2., a dist. of 10.4 ft. (2 blazes)

A white oak, 10 ins. diam., bears S.37°11"F., " " 26.5 ft. (2 blazes)

By computation and protraction, partailly sub-divided the SE 1/4 of the Section as shown. The northerly line of surveyed tract falls southerly of an older fence, by several feet.

Monuments set being 5/8 in iron pins, set approx. flush with the surface.

> RECEIVED JUN 2 1978

SURVEYO