

## SURVEY NARRATIVE TO COMPLY WITH PARAGRAPH 209.250 OREGON REVISED STATUTES

SURVEY FOR:

Terry McCardle

P.O. Box 40 Medford, Oregon 97501

LOCATION:

Section 11 BB, Township 37 South, Range 2 West,

Willamette Meridian, Jackson County, Oregon

PURPOSE:

To survey, monument, and describe the two parcels

shown on the attached map per client's request

PROCEDURE:

Encompassed Block 23 with a closed traverse

(1:28,110) locating and tieing in various monuments from Recorded Survey No. 1465, 1608, and 3106. All monuments set previously on the centerline of Cedar Street have been destroyed. Various attempts were made to recreate the centerline of Cedar Street with the best available evidence being that of splitting the existing curb returns at Second Street and Front Street. Block 23 was proportioned and monuments set as shown on the attached map.

Basis of bearing--Recorded Survey No. 3106

January 5, 1978



REGISTERED PROFESSIONAL LAND SURVEYOR RICHARD L BATH No. 1069

> Richard L. Bath Hoffbuhr Surveying, Inc.