



REGISTERED
PROFESSIONAL
 LAND SURVEYOR

G. W. Plumb

OREGON
 JULY 12, 1968
 G. W. PLUMB

JACKSON COUNTY
 RECEIVED
 APR 04 1978
 SURVEYOR

PROPERTY SURVEY

SITUATE IN

SE 1/4 SEC 9 T 35S R 4W WM

JACKSON COUNTY OREGON

G W PLUMB LAND SURVEYOR MEDFORD OREGON

SCALE 1" = 200'

20 MAR 1978

7196

Survey for E. B. BROWN
1851 Hobart Drive
Camarillo, California 93010

Survey by G. W. Plumb Land Surveyor
P. O. Box 904
Medford, Oregon 97501

Location SE $\frac{1}{4}$ Section 9, Township 35 South, Range 4 West of
the Willamette Meridian, in Jackson County, Oregon

Found brass capped monument for the South quarter corner of Section 9. Found iron pipe monument for the East sixteenth corner of sections 9 and 16. Found the South Center sixteenth corner per R. S. 121, of Section 9. Found five eighths inch iron rod set per R. S. 6823. Set monuments as shown on the accompanying map to mark the corners of property described in Document 77-19436, Official Records of Jackson County, Oregon using measurements made in the subdivision of the Southeast quarter of Section 9 in making R. S. 4559.

20 March 1978

REGISTERED
PROFESSIONAL
LAND SURVEYOR

G. W. Plumb
OREGON
JULY 12, 1968
G. W. PLUMB
E 62

