## SURVEY NARRATIVE TO COMPLY WITH PARAGRAPH 209.250 OREGON REVISED STATUTES

Survey for:

Rogue River National Forest

P. O. Box 520

Medford, Oregon 97501

Location:

Section corner common to Sections 14, 15,

22 and 23, Township 40 South, Range 1 West, Willamette Meridian, Jackson County,

Oregon.

Basis of bearing:

Based on average bearing to southeast and

southwest bearing trees established during 1973 County Surveyor Remonumentation of this corner.

Procedure:

The original 42 inch diameter pine tree bearing N 70° 00'E, 44.60 feet distance, was removed during road construction. I marked the following new tree to reference

this corner:

A fir 18 inches in diameter bears N 49°E, 33.40 feet distance, scribed

S14 LS1071 BT.

HAROLD L. CENTER Registered Professional Land Surveyor Oregon Certificate No. 1071

PROFESSIONAL LAND BURVEYOR

O R E G O N

MAROLD L. CENTER
JULY 30, 1976

No. 1071

RECEIVED
MAY 3 0 1978

SURVEYOR

## SURVEY NARRATIVE TO COMPLY WITH PARAGRAPH 209.250 OREGON REVISED STATUTES

Survey for:

Rogue River National Forest

P. O. Box 520

Medford, Oregon 97501

Location:

Section corner common to Sections 14, 15, 22 and 23, Township 40 South, Range 1 West, Willamette Meridian, Jackson County,

Oregon.

Basis of bearing:

Based on average bearing to southeast and southwest bearing trees established during 1973 County Surveyor Remonumentation of this corner.

Procedure:

The original 42 inch diameter pine tree bearing N 70° 00'E, 44.60 feet distance, was removed during road construction. I marked the following new tree to reference this corner:

A fir 18 inches in diameter bears N 49°E, 33.40 feet distance, scribed S14 LS1071 BT.

HAROLD L. CENTER Registered Professional Land Surveyor Oregon Certificate No. 1071

PROFESSIONAL LAND SURVEYOR

OREGON
HAROLD L. CENTER
JULY 30, 1976
No. 1071

RECEIVED
MAY 3 0 1978

SURVEYOR