


○ Monuments Found
 ● Set 5/8" x 30" Iron Rod
 Bearings based on Survey No. 4485

Survey for: F. N. Ralph
 7875 E. Evans Creek Rd.
 Rogue River, Ore.

Surveyed by: Robert Mason
 415 Surrey Dr.
 Grants Pass, Ore.

OCT. 15, 1978

SURVEY IN
 NE 1/4 of NW 1/4 Sec. 15, T. 35 S., R. 4 W., W.M.,
 Jackson, County, Oregon



REGISTERED
 PROFESSIONAL
 LAND SURVEYOR
Robert Mason
 OREGON
 JULY 22, 1974
 ROBERT MASON
 1011

Survey Narrative

Survey in the Northeast Quarter of the Northwest Quarter of Section 15, Township 35 South, Range 4 West of the Willamette Meridian, Jackson County, Oregon.

Surveyed for: Mr. F. N. Rolph
7875 East Evans Creek Rd.
Rogue River, Oregon

Surveyed by: Robert Mason
415 Surrey Dr.
Grants Pass, Oregon

Purpose of Survey is to locate the boundary and monument the corners of the Rolph parcel as described by deed provided by Mr. Rolph.

Procedure: Using monuments found from Survey No. 4485, I began the survey at the North Quarter corner of Sec. 15 and traversed the parcel according to the description. The description referred to in defining the Southeast line of the Rolph parcel was based upon a different bearing than used for the remainder of the parcel so that this line was adjusted to conform. The legal description of this parcel is supported by the descriptions of six other descriptions which are each supported by a series of other descriptions, each leaving a bit of the perimeter to the imagination.

Survey conducted with a Lietz TM 20C Theodolite and a 200 foot steel tape.

Survey completed October 15, 1978.

