

MAP OF SURVEY
 LOCATED IN
 N.W. 1/4 of Sec. 01, T38 S, R2W, W.M.
 JACKSON COUNTY, OREGON
 FOR
THOMAS CARLTON
 HOFFBUHR SURVEYING, INC. MEDFORD, OREGON
 BY: RICHARD L. BATH R.P.L.S. NO. 1069
 SCALE: 1" = 100' JUNE 6, 1979
 BASIS OF BEARING: R/S NO. 1047
 O = SET 5/8" x 24" IRON PIN
 ● = FD 5/8" IRON PIN

DATA
 $\Delta = 11^{\circ}02''$
 $R = 2864.789'$

DATA
 $\Delta = 10^{\circ}59'10''$
 $R = 2864.789'$



REGISTERED
**PROFESSIONAL
 LAND SURVEYOR**
Richard L. Bath
 OREGON
 JULY 30, 1976
 RICHARD L. BATH
 No. 1069

0982

SURVEY NO. 7860

SURVEY NARRATIVE TO COMPLY WITH PARAGRAPH 209.250
OREGON REVISED STATUTES

SURVEY FOR: Thomas Carlton
2822 Griffin Creek Road
Medford, Oregon 97501



LOCATION: Northwest one-quarter (1/4) of Section 1, Township
38 South, Range 2 West, Willamette Meridian,
Jackson County, Oregon

PURPOSE: To survey, monument, and redescribe the two tracts
as shown on attached map per client's request

PROCEDURE: Located existing monuments per Recorded Survey No.
118, 1047, and 3344. Also, monuments set on the right of way line
of South Columbus Avenue were located. The North, West, and South
lines of the subject tract were determined from monuments found per
Recorded Survey No. 118. Existing right of way control was used
to determine the remaining boundaries of the subject tract.

Basis of bearing--Recorded Survey No. 1047

June 11, 1979



Richard L. Bath
Hoffbuhr Surveying, Inc.