

SURVEY NO. 797 I

SURVEY NARRATIVE TO COMPLY WITH O.R.S. 209-250

Survey for:

Mike Lower

500 Wagon Trail Drive Jacksonville, Or 97530

Survey by:

Edward A. McGinty, RS.S.

August, 1979 Medford, Or

Basis of Bearing:

Survey No. 2493

Located:

In the NE 1/4 of NE 1/4 of Sec. 1, T38S, R3W

Precedence of Survey:

Found a 5/8 in. iron pin, now commonly known as the Easterly 1/16 corner, betw. Sec's. 1 & 36, from this point traversed easterly to a 2 in. pipe, 8 in. high at the Northeast corner of the Sec. This pipe location was varified by measurement only to bearing trees.

Fir, 36 in. diam., bears Northeasterly 47.9 ft. white oak, 6 in. diam., bears southeasterly 35.4 ft. white oak, 7 in. diam., bears southwestely 47.1 ft. black oak, 7 in. diam., bears Northwesterly, 56.4 ft.

Surveyed tract according to clients instructions, setting $5/8 \times 24$ in. ironppins.

Remarks:

Recommend that the NE cor. of Sec. 1 should be lowered and a fence post set along side, as this monument could become endangered if power co. clearing takes place.



