


R.S. No. M77-308
7030



MAP OF SURVEY
SW 1/4 of SW 1/4 of Sec. 14, Twp. 39S., R. 1 E.W.M.
Jackson County Oregon
for

EDITH GRIMSHAW


SWAIN SURVEYING, INC.

ASHLAND, OREGON

Scale: 1"=20'
Basis of Bearing: N.O.A.A. True Bearing N-S Q. Sec. 14

REGISTERED PROFESSIONAL LAND SURVEYOR
Everett L. Swain
OREGON
JULY 8, 1966
EVERETT L. SWAIN
759

- Found 5/8 inch Iron Pin
Re: R.S. No. 7030
- Set monument as shown



8231

SURVEY NO. _____

SURVEY NARRATIVE TO COMPLY WITH PARAGRAPH 209.250
OREGON REVISED STATUTES

SURVEY FOR: Edith Grimshaw
1180 Bellview Avenue
Ashland, Oregon 97520



LOCATION: Situated in the Southwest quarter of the Southwest quarter of
Section 14, Township 39 South, Range 1 East of the Willamette
Base and Meridian, Jackson County, Oregon.

PURPOSE: To replace a monument set on Recorded Survey No. 7030 which
had been destroyed or covered by driveway construction.

PROCEDURE: From previous data established on Recorded Survey No. 7030
proceeded to reset the monument as shown on the accompanying
map.

January 23, 1980

Swain Surveying, Inc.
Ashland, Oregon



39 1E 14cc