

SURVEY SITUATE IN THE NW 1/4 OF SECTION 6  
T. 36 S., R. 1 W., W.M., JACKSON COUNTY, OREGON

Survey for:  
John J. & Cynthia D. White

Survey by:  
Charles H. Hurst, R.L.S.  
Medford, Oregon


REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Charles H. Hurst*

OREGON  
OCTOBER 30, 1959  
CHARLES H. HURST  
483

JUL 15 1980

SCALE: 1" = 100'



T. 35 S.  
T. 36 S.

Fd. 5/8" iron pin per  
Survey No. 6985

Computes S 901.55' & E 867.08'  
from section corner per O.R.  
75-04938

Fd. 5/8" iron pin  
witness corner per  
Survey No. 6985

Fd. 5/8" iron pin  
per Survey No. 3244

O.R. 75-04938

N 14°41'40" E 38.58'  
S 66°01'20" E 35.00'

N 23°58'40" E 385.68'

N 50°39'40" E 119.10'

N 65°26'20" E 182.40'


N 89°59'40" E 270'

1975 center of  
Rogue River per  
Survey No. 6985

Basis of Brgs.  
Survey No. 6985.

LEGEND

- Set 5/8" x 24" iron pin
- △ Angle points of record
- Other monuments as indicated



SURVEY NARRATIVE TO COMPLY WITH PARAGRAPH  
209.250, OREGON REVISED STATUTES

Survey for: John J. & Cynthia D. White  
11400 Modoc Road  
Central Point, Ore. 97502

Survey by : Charles H. Hurst  
304 South Holly  
Medford, Oregon 97501

Bearings : Based on a tangent of Survey No. 6985 as shown on the  
attached plat.

Purpose : To monument the angle point immediately preceding the  
course to the center of Rogue River as existed in 1975.

Procedure

The monumented angle point was established by random line traverse  
on the basis of deed record courses.

Said angle point falls approximately 8 feet South of a culvert  
invert admitting water into an irrigation ditch.

July 15, 1980

