FOUND BRASS CAP IN MON CASE FOUND BRASS CAP IN MON CASE <u>3</u>6 30 36 **Q**31 T365 \$89043'40" E 2663,41 (RS. 5044 2663,36) BASIS OF BEARING T37S 30 VILLAS ROAD 30 30 515.00 Ø 00 AIRPORT DEED VOLUME 333, PAGE 315 (R.S. 6357 SO°C SO°OO'26" W SCALE I"= 100' ···<u>·</u>¦ 30 515.00 FOUND 1/2" X30" IRON PIPE, NOT OF RECORD, AT CORNER POSITION MONUMENT FOUND SET I"X24"GALV. IRON PIPE, FLUSH, WITH 0 YELLOW PLASTIC CAP MARKED 'PLS 760' RECORDED SURVEY R.S. LINE LOCATED FOUND 2" BRASS CAP * FENCE IRON PIPE EXPOSED 3" SURVEY FOR MEDFORD-JACKSON COUNTY AIRPORT LOCATED IN THE NE 1/4-NE 1/4 SEC.1, T375, R2W, WM JACKSON COUNTY, ORE. SCALE 1"= 100" JERRY R. SWANSON, P.L.S. MEDFORD, OREGON FEBRUARY 82 * * RECEIVED * * REGISTERED Date 2/8/82 BYSK PROFESSIONA This survey Consists of: AND SURVEYOR L sheet(s) Map _ page(s) Narrative JACKSON COUNTY SWANSON 60 SURVEYOR

37 2W 1A

SURVEY NARRATIVE TO COMPLY WITH O.R.S. 209.250

Survey For: Medford-Jackson County Airport

3650 Biddle Road

Medford, Oregon 97501

Survey By: Jerry R. Swanson, P.L.S.

2855 Aldersgate Road Medford, Oregon 97501

Purpose of Survey:

To determine the boundary line of the Airport property just

Easterly of the Orr Subdivision, Villas Road.

Procedure: By traverse, tied the N 1/4, the NE corner and the E 1/4 of Section 1, T. 37 S., R. 2 W., W.M. Deed Volume 333, Page 315,

indicates the private property lying East of the Airport property in this area, with Biddle Road being its Easterly boundary. Set the two property corners as shown on the Map

of Survey.

Equipment: A Kern DKM2 theodolite and a Hewlett-Packard 3805 Distance meter.

Date of Survey:

February 6, 1982.

Basis of Bearing:

Recorded Survey No. 5044, record bearing between the N 1/4 Corner and the NE Corner of Section 1, T37S., R2W., W.M.

Jerry R. Swanson

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 8, 1968 ERRY R. SWANSON 760 * * RECEIVED * *

Date 2/8/82 By 54

This survey Consists of:

______ sheet(s) Map
_____ page(s) Narrative

JACKSON COUNTY
SURVEYOR