

* * RECEIVED * *

Date 6/3/82 By Sk

This survey Consists of:

______ sheet(s) Map

_____ page(s) Marrative

JACKSON COUNTY
SURVEYOR

SURVEY NO. 9301

SURVEY NARRATIVE

MAJOR LAND PARTITION

For:

Murrey A. Dumas 2882 Old Military Rd. Medford, Or 97501 (81-14) Bv:

Edward A. McGinty, PLS

P.O. Box 1531

Medford, Or 97501

February, 1982

LOCATION:

The N.E. 1/4 of Sec. 17, T37S, R2W., WM

(1981 Tax Lot 101 and 102)

BASIS OF BEARING:

Solar Observation traverse line near P.I. of Co. Rd.

PRECEDENCE OF SURVEY:

Old Military Road: The exact location is somewhat vague. In 1926 the county road dept. attempted to re-locate this road on a survey under direction of the County Engineer. This location was discussed with Dale Petrasek of Public Works Dept. The field notes of this survey are in Book 30, Page 51 to 59, also the notes would indicate a bearing was determined by compass.

According to older residence, the East 1/2 of the Northeast 1/4 had been sub-divided by a survey in the early 1920's (see county road). Some of the same boundaries are in conflict with some current surveys.

Survey No. 5975 indicates the south line as being the 1/16 line, which is questionable, also it is apparent that no attempt was made, either to locate the true center line, or the more current center line as shown on the county road survey 1926.

The northerly line shown on survey no. 5975 may be somewhat questionable as to title location but is inmaterial now as the client is the common owner on each side.

This survey is not in conformation of previous survey but only shows the relationship of the private road and the interior division lines and dedication west of the west line of the Tract to the Old Military Road. No attempt was made to determine the legal status onthe exterior boundaries as to passession or other surveys. Monuments Found:

NE. cor. of Sec. 17, being a 2 in. pipe near the Southwest corner of the fence. This location verified by some of the bearings to bearing trees.

The East 1/16 corner between 8/19 according to county survey record being a 5/8 in. iron pin verified by a stump of BT and garage.

Old East 1/16 corner (1920 vintage) found 3/4 in. pipe which was used on the old lots sub-division and old county road survey, also identified by adjoiner.

Survey No. 5975:

Found 5/8 in. iron pin approx. flush with the surface and apparently undisturbed. The West line shown N.4°11'00" E., 333.81 ft. measured N.4°12'49" E., 333.83 feet.

OREGON
JULY 10, 1953
EDWARD A. MCGINTY
301

REGISTERED
PROFESSIONAL
LAND SURVEYOR

37 2W 17