

SURVEY NARRATIVE TO COMPLY WITH PARAGRAPH 209.250 OREGON REVISED STATUTES

SURVEY FOR:

City of Medford 411 West 8th Street

Medford, Oregon 97501

BASIS OF BEARING:

R.S. #6410

LOCATION:

Northwest quarter (1/4) of Section 18, Township 37 South, Range 1 West, Willamette Meridian, Jackson

County, Oregon.

PURPOSE:

To survey and locate the newly acquired right-of-way (Poplar Drive) adjoining the Harry Lydiard

property.

PROCEDURE:

Found the re-established corner monument marking

the true location of the southeast corner of D.L.C. 38, T37S, RIW W.M. and the northeast property pin of Survey #6410. Acquired the property acquisition map of the City (denoting the right-of-way of Poplar Drive). With this information, I set the corners as shown on the accompanying plat. On Survey #6410, the pipe shown at 38.22 feet, N89⁰58'50"W from the NE corner, was found and to complete this survey, I reset a 1/2" pin for the corner \$70⁰29'30"W, 75.40 feet from said pipe.

November 8, 1982

** RECEIVED **

Date 11/12/82 BySIC

This survey Consists of:

_____ sheet(s) Map

____ page(s) Narrative

JACKSON COUNTY
SURVEYOR

OREGON

JAN. 12. 1962

C, LIND MCBETH

565

SURVEYOR

REGISTERED PROFESSIONAL

LAND

C. Lind McBeth Professional Land Surveyor