


SURVEY FOR WILLIAM GOIN

NE 1/4 Sec. 20, T38S, R1W, W.M.
Jackson County, Oregon
April 1983

9604



See Survey
No. 9498

LEGEND

- Monument of record
- Set 5/8" x 24" l. pin w/cap stamped L.S. 505

Basis of Bearings: Survey 5364

** RECEIVED **
Date 5/11/83 By SK
This survey consists of:
1 sheet(s) Map
1 page(s) Narrative
JACKSON COUNTY
SURVEYOR

REGISTERED
PROFESSIONAL
LAND SURVEYOR
Verlyn Thomas
CREGON
MAY 13, 1960
VERLYN D. THOMAS
505

9604

Survey by Verlyn Thomas, Professional Land Surveyor, Medford, Oregon

SE 1/4 20

SURVEY NO. 9694

SURVEY NARRATIVE TO COMPLY WITH O.R.S. 209.250

For: William Goin
2373 Pioneer Road
Talent, Oregon

Purpose: To locate and describe an existing fence line for purposes of a Boundary Line Adjustment.

Procedure: Survey control for this area had recently been established by this office in performing Survey No. 9498. From this control, located existing fence line and set monuments as shown on the accompanying plat.

A Boundary Line Agreement for this line is recorded as Instrument No. 83-06068. County Planning File No. 83-38-LLA

