SURVEY NARRATIVE TO COMPLY WITH ORS 209.250

SURVEY FOR:

Gerold Erlinger

P.O. Box 722

Shady Cove, OR 97539

LOCATION:

A portion of the South one-half (1/2) of the Northwest one-quarter (1/4) of Section 15, Township 34 South, Range 1 West, Willamette Meridian, Jackson

County, Oregon.

PURPOSE:

To survey and monument the boundaries of the client's property.

PROCEDURE:

After finding various monuments set during Surveys 291, 3964 and 8024, I ran a traverse from the one-qarter (1/4) corner between sections 15 and 16 to said corners. While reviewing the deeds in this area, it was discovered that the bearing calls to said one-quarter (1/4) corner are off by approximately 1°30'. This fact was also discovered during Survey No. 3964. I tied to various fence lines in the area of this Survey to verify that the error was strictly deed bearings.

The found 1" pin which is 92.39 feet West of the computed corner between Government Lots 3 and 4 (called a 3/4" pipe in Surveys No. 291 and 3964) is at an old fence corner. It is obvious by my ties to various fences in this area that this 1" pin has been used in many deeds as being 100 feet West of the corner between Government Lots 3 and 4.

The 5/8" pin which was found 60 feet West of the client's Southwest corner was pointed out to me by the owner of the property as being his Southeast corner since 1949. He did not know how long before that that the corner was set.

DATE: August, 1983

JOB: #83-137 ERLINGER, GEROLD FRIAR-MOFFIT & ASSOCIATES 717 West 10th, Suite 1 Medford, OR 97501

* * RECEIVED * *

Date 8/18/83 BySC

This survey Consists of:

_______ sheet(s) Map

______ page(s) Narrative

JACKSON COUNTY
SURVEYOR

PROFESSIONAL LAHD SURVEYOR

OREGON

944

REGISTERED