

SURVEY NO. 9928

NARRATIVE

CORNER RESTORATION

April 15, 1984

For: Mountain Fir Lumber Co., Inc.
8890 Williams Highway
Grants Pass, OR 97526

By: Edward A. McGinty
Prof. Land Surveyor
P.O. Box 1531
Medford, OR 97501

1/4 COR. BETWEEN SECS. 8/17, T39S, R3W., WM.

The General Land Office monument, marking this corner, was pulled out in the course of logging operations.

This monument being an iron pipe 1 in. in diam., 36 ins. long with a 2 1/2 ins. Brass Cap, mkd. 1/4 S S 8/17 - 1918 (note, survey was executed in 1917) was reset in its original position, using evidence of hole reset pipe 10 ins., exposed, in a rock mound

Original Bearing trees:

Douglas Fir stump, 20 ins. diam., bears S.30°E., 5.11 ft. (rec. S.30°E., 5.2 ft) with scribe 1/4S (4.70 ft. to face of scribe)



Douglas Fir stump, 20 ins. diam., (sawed off approx at bottom of orig. blaze) bears N.84°W., 9.1 ft. (rec. N.70°W., 9.2 ft.)

New trees:

Douglas Fir, 16 ins. diam., bears S.46 1/2° W., 72.80 ft., mkd 1/4 S 17 B T

Douglas Fir, 16 ins. diam., bears N.84°W., 99.3 ft., mkd. 1/4 S 8 B T
Var. 22°

This corner lies near the head of small ravine, approx. 100 ft. westerly of a logging road running North and Northwest.



SURVEY NO. 9928

NARRATIVE
CORNER RESTORATION

April 15, 1984

For: Mountain Fir Lumber Co., Inc.
8890 Williams Highway
Grants Pass, OR 97526

By: Edward A. McGinty
Prof. Land Surveyor
P.O. Box 1531
Medford, OR 97501

1/4 COR. BETWEEN SECS. 8/17, T39S, R3W., WM.

The General Land Office monument, marking this corner, was pulled out in the course of logging operations.

This monument being an iron pipe 1 in. in diam., 36 ins. long with a 2 1/2 ins. Brass Cap, mkd. 1/4 S S 8/17 - 1918 (note, survey was executed in 1917) was reset in its original position, using evidence of hole reset pipe 10 ins., exposed, in a rock mound

Original Bearing trees:

Douglas Fir stump, 20 ins. diam., bears S.30°E., 5.11 ft. (rec. S.30°E., 5.2 ft) with scribe 1/4 S (4.70 ft. to face of scribe)

Douglas Fir stump, 20 ins. diam., (sawed off) approx at bottom of orig. blaze) bears N.84°W., 9.11 ft. (rec. N.70°W., 9.2 ft.)

New trees:

Douglas Fir, 16 ins. diam., bears S.46 1/2° W., 72.80 ft., mkd 1/4 S 17 B T

Douglas Fir, 16 ins. diam., bears N.84°W., 99.3 ft., mkd. 1/4 S 8 B T
Var. 22°

This corner lies near the head of small ravine, approx. 100 ft. westerly of a logging road running North anNorthwest.

